

Pole Gate Warning 11/4/03

This hazard should be discussed with your people.

It has come to our attention that several incidents have occurred this way in the oilfield. What happens is that people leaving a location fail to notice the single pole gate has swung and is aiming toward their vehicle. They then proceed to impale the vehicle on the pole. Sometimes they impale more than just the vehicle as shown;

